

FIG. 1




FIG. 2A

〈BEFORE OPERATION〉

| ADDRESS | CONTENT OF STACK MEMORY |
|-------------|-------------------------|
| SP → 0x1014 | DATA TO BE OPERATED |
| 0x1010 | DATA TO BE OPERATED |
| 0x100C | SUCCEEDING DATA |
| 0x1008 | SUCCEEDING DATA |
| 0x1004 | SUCCEEDING DATA |
| ... | |

DO NOT PUBLISH OR DISTRIBUTE

FIG. 2B

〈AFTER OPERATION〉

| ADDRESS | CONTENT OF STACK MEMORY |
|-------------|-------------------------|
| 0x1014 | |
| SP → 0x1010 | RESULTANT DATA |
| 0x100C | SUCCEEDING DATA |
| 0x1008 | SUCCEEDING DATA |
| 0x1004 | SUCCEEDING DATA |
| ... | |

FIG. 3




FIG. 4




FIG. 5





FIG. 6



P092165378-4123100

FIG. 7




FIG. 8A

<BEFORE OPERATION>




FIG. 8B

<AFTER OPERATION>




FIG. 9




FIG. 10




FIG. 11




FIG. 12

